TEACHER'S HANDBOOK OF MANUAL TRAINING: METAL WORK

Published @ 2017 Trieste Publishing Pty Ltd

ISBN 9780649503766

Teacher's Handbook of Manual Training: Metal Work by J. S. Miller

Except for use in any review, the reproduction or utilisation of this work in whole or in part in any form by any electronic, mechanical or other means, now known or hereafter invented, including xerography, photocopying and recording, or in any information storage or retrieval system, is forbidden without the permission of the publisher, Trieste Publishing Pty Ltd, PO Box 1576 Collingwood, Victoria 3066 Australia.

All rights reserved.

Edited by Trieste Publishing Pty Ltd. Cover @ 2017

This book is sold subject to the condition that it shall not, by way of trade or otherwise, be lent, re-sold, hired out, or otherwise circulated without the publisher's prior consent in any form or binding or cover other than that in which it is published and without a similar condition including this condition being imposed on the subsequent purchaser.

www.triestepublishing.com

J. S. MILLER

TEACHER'S HANDBOOK OF MANUAL TRAINING: METAL WORK



TEACHER'S HANDBOOK OF MANUAL TRAINING METAL WORK

TEACHER'S HANDBOOK OF MANUAL TRAINING

METAL WORK

CONTAINING

Demonstration Lessons of all Tools and Principles ordinarily used in a Manual Training Centre, with full Scheme of Progressive Exercises approved by His Majesty's Inspector of Manual Training Schools, also Plan and Cost of Equipment of a Model Centre adapted to the Government requirements.

BY

J. S. MILLER

Organiser and Instructor of Metal Work to the Reading School Board

UNIVERSITY
WHITTAKER & CO.

2 WHITE HART ST., PATERNOSTER SQ., LONDON, E.C. AND 66 FIFTH AVENUE, NEW YORK

CONTENTS

											PAGR
		Introduction		33	*		*	-	175	2	Хi
		Model Centre	-				•	12	- fi	rontis	piece
Lesson	I.	The Vice, -				9		23		-	1
	2.	The File and F	iling			92	200	3	12	2	7
223	3.	The Scriber and	l Sc	ribing	2	2	211	12	2	3	12
99	4-	Straight-Edge	*			12	2		12	-	13
	5.	The Engineer's	Squ	are	÷	92	20	12	200	-	15
33	6.	The Shears and	Sh	earing		000	23	33		2	17
"	7-	Wing Compasse	s ar	nd Spr	ing	Divi	ders		2	95	19
	8.	The Centre Pur	ich			12	20	32			21
99	9.	The Hammer		-	9	2	20	2		-	22
11	10.	The Chisel and	Chi	pping	÷	82	26	12			25
12	11.	The Scribing B	lock	or Su	rfac	e Ga	uge	(2)			28
10	12.	The Surface Pla	ite	21	-	124		2			30
32	13.	Callipers -	2	320	2	82	20	2			32
2)	14.	The Screw Pres	s ar	d Pur	ichii	ng -	28	12		2	35
11	15.	The Soldering I	Bit a	ind Sc	lder	ing	23	15			37
79	16.	The Drilling M.	achi	ne and	l D	rilling	23	82	929		40
	17.	Pliers	G	-2	3	2	-	12	12	2	45
***	τ8.	Riveting -	3	20	2	9	22	72	929		46
2)	19.	The Hacksaw	3	30	50	10	38	12			48
31	20.	The Forge and	For	ging	2)		20	2			50
"	21.	The Grindstone	and	Grino	ling	52	2.5	42	12	2	57
,,	22.	Stocks and Dies			10 TO		hes	8		3	59

	Visit in	1000		_						0.000			
													PAGE
Lesso	n 23.		Lathe	37 (55)				Turn	ing)			*	64
22	24.		zing or	Har	d Sol	derin	g	•	-				69
22	25.		dening		•		*				27	32	72
33	26.		ealing				02		*	•		170	74
**	27.	The	Tempe	ring	of S	teel		*	13				75
22	28.	We	lding	•			9	20	92				78
22	29.	The	Proper	ties	of Ca	ist li	ron	*	3	12	-		80
33	30.	The	Proper	ties	of W	roug	ht Ire	n	02		20		82
***	31.	The	Proper	ties	of St	eel			2	+			83
**	32.	The	Blast 1	Furn	ace a	ind l	Manuf	acture	e of	Cast	Iron		84
**	33-	The	Puddli	ng I	urna	ce ar	nd M	anufa	cture	of \	Wroug	ht	
	0.77	85°	Iron	*				-	-			-	88
35	34-		Manuf							():		•	91
,,,	35.	00/3800	Manuf						\$5,			•	94
,,	36.	The	Proper	ties	of Co	pper,	Bras	s, Tit	ı, Zi	nc ar	d Le	ad	96
"	37-	25027	Preser					erich er		160		-	99
**	38.	The	Iron I	oun	dry—	Cast	ing ar	d Mo	ouldi	ng	*	٠	101
Exerc	ise N	0. 1.	Blade o			ee N	0. 16)	-	-		-	-	104
	29	2.	Set Squ			-8	-	200	2	1.60			105
	21	3-	Hexago	100000	10000000			7.010.15700	-5.00				106
	**	4-	Spanne	r H	ead (Gaug	e for	Hex	agor	al N	uts)		107
	**	5a.	Rivet o	r C	halk	Hold	er (fr	ont)	-				108
	23.	50.	Rivet of	or C	halk	Hold	ler (co	omple	te)	-	12	-	109
	**	6.	Picture	Ho	ok (f	or N	ailing	or S	crew	ring)			110
	11	7-	Picture	Ho	ok (fe	or H	angin	g upo	n a	Mou	lding)	-	111
	22	8a, b.	Rack f	or 3	Sma	dl Fi	les	35	-			-	112
	"	86.	Rack f	or 3	Sma	H Fil	les (c	omple	te)	25	Ş		113
	22	9.	Simple	Inla	ying	and	Gaug	e for	He	agon			114
	22.	10a, b.	Letter	Racl	k -			20	2		9		115
	99.	100.	Letter			mplet	te)	26	ŵ	56			116
	73.	11.	Cold F			330.00			99		2		117
	55	12.	Match	Hol	der	- S	- 12	56	12	13	12		118

÷ 3